

Annexure D**BUILDING SAFETY CERTIFICATE**No. **06/AE/RED/2025-26**Dated: **01.05.2025**

It is certified that the Existing building **St. Anthony's School** at **Dugawar ,Post- Asmoli, Dist. Sambhal ,U.P.** is having block(s) Floor(s) as per details below.

Detial of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (15)	Block (6)
No.of Floor(s) in the Block	2 Ground Flor First Floor	3 Ground Floor First Floor Second Floor	1 Ground Floor			

This building is owned /occupied by **St. Anthony's School** have complied with the building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **Rural Engineering Department Sambhal at Bahjoi** on 01.05.2025 in the presence of **Roy Mathews T (Manager) St. Anthony's School, Dugawar, Post-Asmoli, Dist.Sambhal,U.P.** and that the building/premises is fit for occupancy for running school with effect from **01.05.2025** for a period of **3 years** in accordance with rule and subject to compliance of specific conditions as appended .

1. Continuous monthly maintenance of building during above period .
- 2.Continuous Cleaning of rain water pipes and roof & top before rains.
3. During above Period if any cracks seen in building, information to be given to department for further inspection for instruction.
4. Executive Engineer of Rural Engineering Department Sambhal already issued NBC as per letter no. 953 dated 22.03.2021 .

Issued on:- **01.05.2025** at **Bahjoi** by **Ramgopal (Assistant Engineer)Rural Engineering Department Sambhal at Bahjoi,U.P.**

Signature with Seal:

Name: **Ramgopal**Designation: **Assistant Engineer**

Name and Address of

Department/Office : **Rural Engineering**

Department Sambhal at Bahjoi,U.P.


Manager

St. Anthony's Sr Sec School
Dugawar Asmoli Sambhal (U P)


The Principal

St. Anthony's Sr. Sec. School
Dugawar, Asmoli, Sambhal